

---

# **XS Upgrade - Verisign SSL Certificate**

Affected products

RL1600, RL2000, RL5000, FT5000,  
RT2000, Traverse, ARGO 7, ARGO 12,  
ARGO 15

August 29, 2016

Version 1.0

**Triton Systems of Delaware, LLC**  
21405 B Street  
Long Beach, MS 39560  
PHONE: (228) 868-1317  
FAX: (228) 868-0437

<b>INTRODUCTION.....</b>	<b>3</b>
<b>PLATFORMS AFFECTED.....</b>	<b>3</b>
HARDWARE SUPPORT .....	3
SOFTWARE REQUIREMENTS .....	3
EXTERNAL DEPENDENCIES .....	3
<b>CHANGES.....</b>	<b>4</b>
VERISIGN CERTIFICATES .....	4
<b>REVISION HISTORY .....</b>	<b>4</b>

## Introduction

This document describes an upgrade load file which allows CE ATMs to communicate with hosts which use newer certificates issued by Verisign. A host is either a transaction processor or Triton Connect.

## Platforms Affected

This release is for the following families:

- XScale, X2 CE5, X2 CE6, X3

## Hardware Support

No specific hardware is required for this software release.

## Software Requirements

The ATM must be running application version 2.4.0 or greater.

The following load files are included with this release:

- t-sw-cavs-2.0.1.tlf – XScale Update
- t-sw-cavs-2.0.1.tfv – X2 CE5 Update
- t-sw-cavs-2.0.1.tr6 – X2 CE6 Update
- t-sw-cavs-2.0.1.tr7 – X3 Update

**IMPORTANT:** After software installation completes, restart the ATM by selecting *Management > System Parameters > Restart Terminal* to apply the new settings.

## External Dependencies

None

## Changes

### ***Verisign certificates***

The following will appear in the configuration summary (for ATMs using software version 4.0 or later):

```
-----  
Subject CN: VeriSign Class 3 Public Primary Certification  
Authority - G5  
Not Before: 11/8/2006 00:00:00  
Not After: 11/7/2021 23:59:59  
Serial Number: 250CE8E030612E9F2B89F7054D7CF8FD  
Thumbprint: 32F30882622B87CF8856C63DB873DF0853B4DD27  
-----
```

## Revision History

Date	Version	Description of Change
August 29, 2016	1.0	Initial