

XScale Modem Update Release Notes

Affected products

RT2000

FT5000

RL5000

March 3, 2011

Version 1.0

Triton Systems of Delaware, LLC
21405 B Street
Long Beach, MS 39560
PHONE: (228) 868-1317
FAX: (228) 868-0437

INTRODUCTION.....	3
PLATFORMS AFFECTED.....	3
HARDWARE SUPPORT	3
SOFTWARE REQUIREMENTS	3
EXTERNAL DEPENDENCIES	3
CHANGES.....	3
ZOOM 3075 PC CARD MODEM SUPPORT	3
REVISION HISTORY	3

Introduction

This document describes functionality of software update to support replacement modem for the XScale systems (RL5000, FT5000 and RT2000).

Platforms Affected

This release is for the following families:

- RL5000, FT5000, and RT2000 with XScale Controller

Hardware Support

- Modems: Zoom 3075 PC Card Modem, MultiTech USB Modem, MultiTech PCMCIA

Software Requirements

The following load files are included with this release:

- xu20xtcm1.0.5.tlf – XScale Modem Update

This update can be installed on any existing version of XScale software (application or operating system). No other software is required.

External Dependencies

None

Changes

Zoom 3075 PC Card Modem Support

This update provides support for the Zoom 3075 PC Card modem as a replacement modem for the XScale ATMs.

Revision History

Date	Version	Description of Change
March 3, 2011	1.0	Initial