

# XS Upgrade - VeriSign SSL Certificate

Affected products

**RL1600** 

**RL2000** 

**RL5000** 

FT5000

RT2000

October 26, 2010

Version 1.0

Triton Systems of Delaware, LLC 21405 B Street Long Beach, MS 39560 PHONE: (228) 868-1317 FAX: (228) 868-0437

INTRODUCTION	
PLATFORMS AFFECTED	2
HARDWARE SUPPORT	2
SOFTWARE REQUIREMENTS	
External Dependencies	2
CHANGES	3
VERISIGN CLASS 3 CERTIFICATES	
REVISION HISTORY	3

#### Introduction

This document describes an upgrade load file which allows an XScale or X2 ATM to communicate with hosts which use SSL new certificates issued by VeriSign. This upgrade load file is not required for hosts which use any other SSL certificates. A host is either a transaction processor or Triton Connect.

## **Platforms Affected**

This release is for the following families:

• RL1600, RL2000, RL5000, FT5000, or RT2000 with XScale or X2 controllers

### Hardware Support

No specific hardware is required for this software release. It can be loaded on any XScale or X2 system.

### Software Requirements

The ATM must be running application version 2.4.0 or greater.

The following load files are included with this release:

- xt20cavs1.0.0.tlf Support SSL certificates issued by VeriSign (XScale).
- xt30cavs1.0.0.tfv Support SSL certificates issued by VeriSign (X2).

### External Dependencies

None

# Changes

#### VeriSign Class 3 certificates

This software update adds the terminal to support the following VeriSign SSL certificates:

- VeriSign Class 3 Secure Server CA G2 (S-CN)
- Class 3 Public Primary Certification Authority G2 (S-OU)

## **Revision History**

Date	Version	Description of Change
October 26, 2010	1.0	Initial